



Affected Culverts for Proposed Tree Removal



LEVEL 1 CONCERN TREES AT CHOKE POINT AREAS										
LOCATION	Culverts	Diameter	LEVEL 1 CONCERN TREES-UPSTREAM	Natives	Invasives	Non Native-Desirables	Non-Native Invasive	Shrub	RESIDENTIAL AFFECTED	OTHER AFFECTED
E-5	1	72"	13	10		3			21	
E-10	1	72"	87	37	30	17	2	1	15	1 (CITY PARK)
E-13	2	96"	9	2	1	4	2		16	3 (2 APTS:1CITY R/W
E-17	4	48"	3	1	1	1			36	
E-18	1	168"	4		4				4	1(1APTS)
E-19	1	72"	0	0	0	0	0	0	0	3(2APTS:1COMMERCIAL)
E-24	1	72"	2	1		1			22	
W-4	1	60"	1				1		4	
W-5	1	60"	30		29	1			5	2 (SCHOOL: CITY R/W)
W-6	1	54"	0						21	
W-14	1	84"	2		2				3	1(SCHOOL)
W-22	1	84"	0						0	
		Totals:	151	51	67	27			126	10

Level 1 concern "applies to a tree that is likely to expereince failure under normal weather conditions and impact the canal in the event of failure"
(normal weather conditions are winds under 35mph) (condition is already considered in the level of concern rankings)

Level 1 Concerns at Culvert E5




Species	Condition	Native	Invasive	Non-Native Desirable	Non-Native Invasive	Shrub	Height (ft)	Diameter	Canopy Size	Address
Areca Palm	Good			x			25	Diameter Not Required	30x30	8499 NW 14th Ct
Mango Tree	Fair			x			20	13	30x30	8499 NW 14th Ct
Sabal Palm	Poor	x					7	Diameter Not Required	12x12	8497 NW 15th Ct
Sabal Palm	Poor	x					12	Diameter Not Required	12x12	8497 NW 15th Ct
Strangler Fig	Poor	x					35	29	60x60	1619 NW 85th Dr
Stranger Fig	Poor	x					40	50	60x60	1555 NW 85th Dr
Sabal Palm	Poor	x					15	Diameter Not Required	12x12	1555 NW 85th Dr
Sabal Palm	Poor	x				10 & 25 (double trunk)		Diameter Not Required	12x22	1555 NW 85th Dr
Sabal Palm	Poor	x					2	Diameter Not Required	6x6	1547 NW 85 Dr
Sabal Palm	Poor	x					10	Diameter Not Required	12x12	1547 NW 85 Dr
Strangler Fig	Poor	x					35	100	70x70	1529 NW 85 Dr
Sabal Palm	Poor	x					17	Diameter Not Required	24x18	1529 NW 85 Dr
Rubber Fig	Fair			x			60	136.5	100x100	8492 NW 15th Ct

Species	Condition	Native	Invasive	Non-Native Desirable	Non-Native Invasive	Shrub	Height (ft)	Diameter	Canopy Size	Address
Pongam	Poor		x				30	28	60x60	1773 NW 92nd Way
Pongam	Poor		x				22	9	20x18	1701 NW 92nd Way
Pongam	Poor		x				20ft	18in	32x15	1701 NW 92nd Way
Pongam	Poor		x				20ft	14in	36x18	1701 NW 92nd Way
Pongam	Poor		x				20ft	14in	24x15	1701 NW 92nd Way
Pongam	Poor		x				25	21	30x22	1701 NW 92nd Way
Pongam	Poor		x				25	28	30x15	1701 NW 92nd Way
Pongam	Poor		x				18	17	30x15	1701 NW 92nd Way
Kuntze	Poor					x	12	11	15x8	1701 NW 92nd Way
Slash Pine	Fair	x					45	24	28x28	9211 NW 16th St
Black Sapote	Poor	x					60	31	60x50	1433 NW 92nd Way
Royal Poinciana	Poor	x					30	19	60x30	1433 NW 92nd Way
Bishopwood	Poor		x				40	27	70x30	1433 NW 92nd Way
Hong Kong Orchid	Poor				x		15	9.5	18x6	1433 NW 92nd Way
Ficus Nitida	Poor				x		65	68	75x75	1957 Coquina Way
Stranger Fig	Poor	x					25	5	18x6	1600 NW 91st Ave
Live Oak	Fair	x					30	7	18x15	1600 NW 91st Ave
Schefflera	Poor		x				25	1.5	6x6	1600 NW 91st Ave
Schefflera	Poor		x				5	2	6x6	1600 NW 91st Ave
Sea Grape	Fair	x					17	3.5	18x6	1600 NW 91st Ave
Live Oak	Poor	x					18	3	12x6	1600 NW 91st Ave
Live Oak	Poor	x					18	4.5	19x6	1600 NW 91st Ave
Slash Pine	Fair	x					28	6	18x18	1600 NW 91st Ave
Laurel	Poor	x					15	3.5	11x8	1600 NW 91st Ave
Black Olive	Poor			x			15	1.5	12x6	1600 NW 91st Ave
Live Oak	Poor	x					25	3.5	20x18	1600 NW 91st Ave
Black Olive	Poor			x			15	4	18x9	1600 NW 91st Ave
Laurel	Fair	x					45	14	35x30	1600 NW 91st Ave
Live Oak	Poor	x					18	3.5	Na	1600 NW 91st Ave
Live Oak	Poor	x					27	6	24x16	1600 NW 91st Ave
Sea Grape	Poor	x					18	4	20x18	1600 NW 91st Ave
Sea Grape	Poor	x					14	5	17x9	1600 NW 91st Ave
Slash Pine	Fair	x					55	13.5	30x30	1600 NW 91st Ave
Live Oak	Fair	x					35	11.5	30x23	1600 NW 91st Ave
Fiddle Leaf Fig	Poor			x			18	2.5	18x12	1600 NW 91st Ave
Live Oak	Poor	x					15	3.5	18x9	1600 NW 91st Ave
Black Olive	Poor			x			15	3	18x10	1600 NW 91st Ave
Brazilian Pepper	Poor		x				18	0.5	12x6	1600 NW 91st Ave
Live Oak	Fair	x					27	15	30x30	1600 NW 91st Ave
Pongam	Poor		x				17	1.5	12x6	1600 NW 91st Ave
Black Olive	Poor			x			6	2	3x3	1600 NW 91st Ave
Black Olive	Fair			x			30	7	22x18	1600 NW 91st Ave
Black Olive	Poor			x			22	4.5	18x12	1600 NW 91st Ave
Live Oak	Poor	x					14	2.5	12x4	1600 NW 91st Ave
Stranger Fig	Poor	x					22	2	18x6	1600 NW 91st Ave
Live Oak	Poor	x					35	7	22x16	1600 NW 91st Ave
Live Oak	Poor	x					20	3	24x18	1600 NW 91st Ave
Live Oak	Poor	x					15	2	8x3	1600 NW 91st Ave
Schefflera	Poor		x				19	6	8x6	1600 NW 91st Ave
Bottlebrush	Poor			x			7	6.5	18x12	1600 NW 91st Ave
Australian Pine	Poor		x				8	4.5	20x3	1600 NW 91st Ave
Stranger Fig	Poor	x					32	23.5	30x28	1600 NW 91st Ave
Stranger Fig	Poor	x					15	3.5	12x6	1600 NW 91st Ave
Brazilian Pepper	Poor		x				11	11.5	24x22	1600 NW 91st Ave
Bald Cypress	Poor	x					18	4	12x6	1600 NW 91st Ave
Stranger Fig	Poor	x					3	1.5	4x2	1600 NW 91st Ave
Stranger Fig	Poor	x					22	5	18x6	1600 NW 91st Ave
Live Oak	Poor	x					14	2.5	18x6	1600 NW 91st Ave
Brazilian Pepper	Poor		x				15	0.5	5x3	1600 NW 91st Ave
Brazilian Pepper	Poor		x				8ft	3.5in	24x8	1600 NW 91st Ave
Live Oak	Poor	x					18	3	18x12	1600 NW 91st Ave
Stranger Fig	Poor	x					26	5.5	18x11	1600 NW 91st Ave
Pongam	Poor		x				25	7.5	24x16	1600 NW 91st Ave
Pongam	Poor		x				30	9	30x22	1600 NW 91st Ave
Pongam	Poor		x				25	5.5in	24x24	1600 NW 91st Ave
Pongam	Poor		x				20	5	26x18	1600 NW 91st Ave
Bishopwood	Poor		x				35	8	26x18	1600 NW 91st Ave
Pongam	Poor		x				32ft	9.5in	34x28	1600 NW 91st Ave
Pongam	Poor		x				35ft	11in.	38x24	1600 NW 91st Ave
Schefflera	Poor		x				20	3.5	6x6	1600 NW 91st Ave
Black Olive	Poor			x			35	8	25x22	1600 NW 91st Ave
Stranger Fig	Fair	x					35	7.5	30x26	1600 NW 91st Ave


Pongam	Poor		x				17	12	28x12	1600 NW 91st Ave
Schefflera	Poor		x				18	6	12x10	1600 NW 91st Ave
Strangler Fig	Poor	x					25	16	28x22	1600 NW 91st Ave
Pongam	Fair		x			28ft		7in.	32x32	1600 NW 91st Ave
Slash Pine	Fair	x					30	19	40x40	1600 NW 91st Ave
Black Olive	Fair			x			45	17	60x60	1600 NW 91st Ave
Black Olive	Poor			x			45	13.5	60x40	1600 NW 91st Ave
Bottlebrush	Poor			x			12	3	18x6	1600 NW 91st Ave
Sea Grape	Fair	x					16	1.5	18x12	1600 NW 91st Ave
Black Olive	Poor			x			45	14.26	60x45	1600 NW 91st Ave
Black Olive	Poor			x			12	2.5	18x10	1600 NW 91st Ave
Black Olive	Poor			x			30	7	40x22	1961 Coquina Way
Bishopwood	Poor		x				12	2	16x9	1961 Coquina Way
Black Olive	Poor			x			40	12	60x36	1961 Coquina Way
Black Olive	Poor			x			40	28	80x60	1961 Coquina Way

Level 1 Concerns at Culvert E13




Species	Condition	Native	Invasive	Non-Native Desirable	Non-Native Invasive	Shrub	Height (ft)	Diameter	Canopy Size	Address
Sabal Palm	Poor	x					5	Diameter Not Required	12x12	1136 NW 90th Ln
Bishopwood	Poor		x				7ft	2.5in	20x0	1128 NW 90th Ln
Sea Grape	Poor	x					60	45	60x40	1228 NW 91st Ave
Ficus Nitida	Poor				x		60	60	80x80	1280 NW 91st Ave
Ficus Nitida	Poor				x		30	41	80x60	1314 NW 91st Ave
Longan	Poor			x			55	27	60x60	1368 NW 91st Ave
Ficus Elastica/Rubber Tree	Poor			x			60	135	80x60	1373 NW 92nd Ter
Ficus Elastica/Rubber Tree	Poor			x			60ft	140	80x60	1373 NW 92nd Ter
Mango Tree	Poor			x			20ft	10in	25x20	9210 NW 13rd Pl

Level 1 Concern at E-17




Species	Condition	Native	Invasive	Non-Native Desirable	Non-Native Invasive	Shrub	Height (ft)	Diameter	Canopy Size	Address
Copper Pod	Poor	x					27	14	24x24	9199 NW 1st St
Bishopwood	Poor		x				50	37	60x60	9133 NW 1st St
Mango Tree	Fair			x			28	8.5	26x26	9073 NW 1st S

Level 1 Concerns at Culvert E18




Species	Condition	Native	Invasive	Non-Native Desirable	Non-Native Invasive	Shrub	Height (ft)	Diameter	Canopy Size	Address
Brazilian Pepper	Poor	x					20	14	26x12	377 NW 93rd Ave
Brazilian Pepper	Poor	x					25	22	35x20	415 NW 93rd Ave
Pongam	Poor	x					20	19.5	30x18	415 NW 93rd Ave
Sea Hibiscus	Poor	x					18	12	22x16	431 NW 93rd Ave

Level 1 Concerns at Culvert E24




Species	Condition	Native	Invasive	Non-Native Desirable	Non-Native Invasive	Shrub	Height (ft)	Diameter	Canopy Size	Address
Ficus	Poor			x			65	48	80x80	10032 Vestal Pl
Mahogany	Poor	x					55	26	60x60	1862 NW 97th Ter

Level 1 Concerns W4 Culvert



Species	Condition	Native	Invasive	Non-Native Desirable	Non-Native Invasvie	Shrub	Height ft)	Diameter	Canopy Size	Address
Ficus Nitida	Fair				x		49	80	100x100	176 NW 114th

Level 1 Concerns at Culvert W-5 & W-6



SW 114th Ter

W-6

W-5

NW 113th Way

NW 1st Pl

Riverside Dr


Riverside Dr

NW 1st Ct

NW 1st Ct

Species	Condition	Native	Invasive	Non-Native Desirable	Non-Native Invasive	Shrub	Height (ft)	Diameter	Canopy Size	Address
Java Plum	Poor		x				45	34	80x60	11450 Riverside Dr
Java Plum	Poor		x				45	32	80x40	11450 Riverside Dr
Java Plum	Poor		x				45	36	80x40	11450 Riverside Dr
Java Plum	Poor		x				45	33	80x40	11450 Riverside Dr
Java Plum	Poor		x				45	37	80x40	11450 Riverside Dr
Java Plum	Poor		x				45	32	80x40	11450 Riverside Dr
Java Plum	Poor		x				45	32	80x40	11450 Riverside Dr
Java Plum	Poor		x				45	36	80x40	11450 Riverside Dr
Java Plum	Poor		x				45	33.5	80x40	11450 Riverside Dr
Java Plum	Poor		x				45	36	80x40	11450 Riverside Dr
Java Plum	Poor		x				45	32	80x40	11450 Riverside Dr
Java Plum	Poor		x				45	32	80x40	11450 Riverside Dr
Java Plum	Poor		x				45	31.5	80x40	11450 Riverside Dr
Java Plum	Poor		x				45	36	80x40	11450 Riverside Dr
Java Plum	Poor		x				45	38	80x40	11450 Riverside Dr
Java Plum	Poor		x				45	36.5	80x40	11450 Riverside Dr
Java Plum	Poor		x				45	36.5	80x40	11450 Riverside Dr
Earleaf Acacia	Fair		x				60	24	70x60	11450 Riverside Dr
Java Plum	Poor		x				45	29	80x40	11450 Riverside Dr
Java Plum	Poor		x				45	36	80x40	11450 Riverside Dr
Java Plum	Poor		x				45	34	80x40	11450 Riverside Dr
Java Plum	Poor		x				45	34.5	80x40	11450 Riverside Dr
Java Plum	Poor		x				45	34.5	80x40	11450 Riverside Dr
Java Plum	Poor		x				45	37	80x40	11450 Riverside Dr
Java Plum	Poor		x				45	24	80x40	11450 Riverside Dr
MacArthur Palm	Fair			x			8	Diameter Not Required	10x10	11450 Riverside Dr
Javaplum	Poor		x				45	24	80x40	11450 Riverside Dr
Javaplum	Poor		x				45	37	80x40	11450 Riverside Dr
Javaplum	Poor		x				45	34.5	80x40	11450 Riverside Dr
Javaplum	Poor		x				45	34.5	80x40	11450 Riverside Dr

Level 1 Concerns at Culvert W14



Species	Condition	Native	Invasive	Non-Native Desirable	Non-Native Invasvie	Shrub	Height (ft)	Diameter	Canopy Size	Address
Brazillian Pepper	Poor		x				10	2.5	12x9	908 NW 114th
Brazillian Pepper	Poor		x				12	3.5	8x8	875 CORAL RIDGE DR